

# 1/6

**D100 / K220**  
**No.: 81202 / 80mm**



Duration : 6min  
Speed: 9360 U/min

Pressure :  
1st minute = Machine weight  
2nd - 6th minute= light pressure

# 2/6

**D30 / K600**  
**No.: 81205 / 80mm**



Duration : 6min  
Speed: 9360 U/min

Pressure :  
1st minute = Machine weight  
2nd - 6th minute= light pressure

# 3/6

**D16 / K1200**  
**No.: 81206 / 80mm**



Duration : 6min  
Speed: 9360 U/min

Pressure :  
1st minute = Machine weight  
2nd - 6th minute= light pressure

# 4<sub>/6</sub>

**D06 / K2000**  
**No.: 81207 / 80mm**



Duration : 6min  
Speed: 9360 U/min

Pressure :  
1st minute = Machine weight  
2nd - 6th minute= light pressure

# 5<sub>/6</sub>

**Berry**  
**No.: 10118 / 60mm**



Duration : 7min  
Speed: 9360 U/min

Pressure :  
1st minute = Machine weight until the paste is liquid  
2nd - 7h minute= light pressure

# 6<sub>/6</sub>

**Sun**  
**No.: 10119 / 60mm**



Duration : 10min  
Speed: 9360 U/min

Pressure :  
1st minute = Machine weight until the paste is liquid  
2nd - 10h minute= light pressure